



17-107



Tactical Vehicle Mishap Claims One Soldier's Life

A 27-year-old Specialist assigned to 1st Armored Division, Fort Bliss, Texas, died 22 September 2017 on Fort Bliss at 1223 local. The Soldier was operating an M978 Fuel Tanker in dust conditions during a convoy movement when his vehicle collided with the rear of a preceding M1120A4 Load Handling System.

PLRs provide leaders with awareness of Army loss and highlight potential trends that affect combat readiness. Our Army depends on you to use these PLRs to help Soldiers understand the impact of decisions made on and off duty.

The U.S. Army Combat Readiness Center wants your feedback. Please click here to provide comments on PLRs. Additional resources can be found on the USACRC website at <https://safety.army.mil>.

PRINT IT

ANALYZE IT

TRAIN IT

